



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L03-63

Date: 5 SEPTEMBER 2003

Waterway: LAKE HURON

Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL
CASEVILLE HARBOR

1. Condition surveys performed within the Federal navigation channel at Caseville Harbor, Michigan during July 2003, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L03-63. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Home Page.

THOMAS H. MAGNESS
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2003.



The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: JULY 2003

0casevil.bmp



Shoals indicate least available depth below I.G.L.D.

All depths and project depths are referred to Low Water Datum elevation 577.5 ft. above Mean Water Level, IGLD, 1985.

CASEVILLE HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 5 SEPTEMBER 2003

U.S. Army Engineer District, Detroit